

VICINITY MAP
(N.T.S.)


FLOOD CERTIFICATION

THIS WILL CERTIFY THAT THE SUBJECT PROPERTY () IS or (X) IS NOT located in a SPECIAL FLOOD HAZARD AREA as determined by the Department of Housing and Urban Development, or as shown on the FLOOD INSURANCE RATE MAP.

370243 1830 J
COMMUNITY # PANEL SUFFIX PROFESSIONAL LAND SURVEYOR

[Signature]

CURVE TABLE			
CURVE	LENGTH	RADIUS	DELTA
C1	74.46'	297.50'	14°20'26"
C2	26.81'	20.00'	76°48'54"
C3	45.61'	550.00'	4°45'06"
C4	56.92'	300.00'	10°52'12"




LINE TABLE		
LINE	LENGTH	BEARING
L1	25.19'	S78°55'27"E
L2	5.41'	S37°13'52"E



VILLAGE MANOR WAY
(45' R/W)

VILLAGE SPRINGS ROAD
(50' R/W)



LEGEND

- EXISTING IRON PIPE
- NEW IRON PIPE
- × COMPUTED CORNER

NOTE:

THIS PROPERTY DOES NOT LIE WITHIN 2000' OF A N.C.G.S. MONUMENT.

THIS SURVEY IS OF AN EXISTING PARCEL OR PARCELS OF LAND.

UTILITIES SHOWN ARE FOR REPRESENTATION ONLY AND NOT TO BE USED FOR PROPERTY LINE LOCATION

ALL CREEKS, EASEMENTS, BUFFERS, FLOOD LIMITS & SETBACKS TAKEN FROM BOM 2004, PG 676

S 82°44'56" W 135.39'
TIE TO THE CENTERLINE
INTERSECTION OF VILLAGE
MANOR WAY & VILLAGE
SPRINGS ROAD

LOT 49

I, Jeffrey H. Davis, PLS, certify this map was drawn under my supervision from an actual survey made under my supervision; and that the error of closure as calculated by latitudes and departures is 1/10,000+; that the boundaries not surveyed are shown as broken lines plotted from information found in Book ; Page ; that this map was prepared in accordance with G.S. 47-30 amended.

[Professional Seal]
JEFFREY H. DAVIS
SURVEYOR